// MKCA //

IO4 EAST IOTH STREET

COMMUNITY BOARD 3

LANDMARKS SUBCOMMITTEE

AUGUST 25, 2023

// 104 E 10TH ST //

### 104 EAST 10TH STREET // COMMUNITY BOARD 3 LANDMARKS SUBCOMMITTEE



ARCHITECT

// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

SCALE: 1" = 6"

DATE:


19\_104E10 PROJECT NO:

FILE NAME:

| SHEET:

© 2023 MICHAEL K. CHEN ARCHITECTURE, PLLC

SCALE: N.T.S.



ARCHITECT // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060

eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10 PROJECT NO:

FILE NAME:

| SHEET:







1 DESIGNATION PHOTO - 1984

LPC DESIGNATION REPORT

2 TAX PHOTO - c. 1986 TAX MAP PHOTO (VIA MUNICIPAL ARCHIVES) 3 CONDITION BEFORE RENOVATION - MARCH 2019
PHOTO BY ARCHITECT

ARCHITECT
// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

**104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10

DWG NO:

<u>LPC -003</u>

FILE NAME:

PROJECT NO:

|SHEET:







AREAWAY CLOSEUP - MARCH 2023 PHOTO BY ARCHITECT

ARCHITECT // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10 PROJECT NO:

FILE NAME:

| SHEET:

#### **Violation Number: VIO-10-0612 (Active)**

Address: 104 East 10th Street **Community District: MN-3** 

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

Violation Date: 12/21/2009 Violation Text: Garden floor window guards

replaced without permit(s).


Violation Status: Warning Letter



**East Window** 

The previosuly installed window guards were replaced without permit and were the impetus for the inital LPC violation.





West Window

GARDEN FL. WINDOWS - RESTORED CONDITION PHOTO BY ARCHITECT

#### NOTES:

All windows at the front facade were replaced with approved, historic equals. Unpermitted window guards at the garden level windows were removed.

There is no historic record of the original design or intent. We know there was a violation filed in 2009 for unpermitted removal and replacement, but the exact nature of the original guards is unknown.

We are requesting to forgo replacement as any reconstruction would need to be derived from seconary references. Further, we believe unguarded windows offer a more consistent and uniform reading across all windows on the front facade and is not in conflict with the aesthetic make up of the block. As you will see in reference photos, there is a mix of guarded and unguarded windows in the St. Marks Historic District.

ARCHITECT

// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

104 E 10th Street 104 E 10th St., New York, NY 10003

### LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

PROJECT NO:

19 104E10

DWG NO:

FILE NAME:

| SHEET:

© 2023 MICHAEL K. CHEN ARCHITECTURE, PLLC

GARDEN FL. WINDOWS - PREVIOUS CONDITION PHOTO BY ARCHITECT

West Window





PHOTO BY ARCHITECT

#### Analysis:

The window guards at neighboring building 102, which together with 104 comprise the totality of the St. Marks historic district extension, seem to be of the same vintage as the non-coforming guards previously installed at 104.





122 E 10th St (No Window Guard)

PHOTO BY ARCHITECT

#### Analysis:

Townhouse 122, located on the same south block as 104, has no window guards installed at the garden level windows.





124 E 10th St (No Window Guard)

PHOTO BY ARCHITECT

#### Analysis:

Similarly, townhouse 124, located on the same south block as 104, has no window guards installed at the garden level windows.

ARCHITECT

## // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10 PROJECT NO:

DWG NO:

FILE NAME:

| SHEET:

#### **Violation Number: VIO-86-0007 (Active)**

Community District: MN-3 Address: 104 East 10th Street

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

Violation Text: The ongoing facade work (incl. Violation Date: 7/10/1985

paint, stripping, etc. Cont.: 'Boge') without

Violation Status: Summons (NOV)







#### NOTES:

An extensive and careful process, as described in filed and approved drawings, was undertaken to restore the masonry facade from it's derelict condition. This included detailed correspondance and multiple on-site metings with preservationist, Katherine Redd, to ensure historic accuracy in terms of overall aesthetic. To everyones surpise, it was determined that the original mortar was a brick color and farily flush with the face of the bricks, resulting in uniformly colored and smooth appearance of the facade.

ARCHITECT

## // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

## **104 E 10th Street**

104 E 10th St., New York, NY 10003

### LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

PROJECT NO:

19\_104E10

FILE NAME:

| SHEET:

© 2023 MICHAEL K. CHEN ARCHITECTURE, PLLC

10TH STREET FACADE - PREVIOUS CONDITION PHOTO BY ARCHITECT

**RESTORATION WORK TO DATE - FACADE** 

#### **Violation Number: VIO-86-0007 (Active)**

Community District: MN-3 Address: 104 East 10th Street

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

Violation Date: 7/10/1985 Violation Text: The ongoing facade work (incl.

paint, stripping, etc. Cont.: 'Boge') without

Violation Status: Summons (NOV)

### Original



Color: Original Condition: Dry

### Top Contender



Color: Venetian Red Condition: Dry



Venetian Red Powder Original Grout Sample (exterior face)



[left] Venetian Red Powder [right] Original Grout Sample Original Grout Sample (interior face)

From: Katherine Redd (LPC) kredd@lpc.nyc.gov &
Subject: RE: [EXTERNAL] East 10th - grout color
Date: December 16, 2021 at 2:31 PM
To: Andrew Matia andrew@mkca.com
Cc: Braden Caldwell braden@mkca.com, Caroline Kane Levy (LPC) CKaneLevy@lpc.nyc.gov, Michael Chen michael@mkca.com

ARCHITECT

// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060

eastcoast@mkca.com

PROJECT

**104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19 104E10 PROJECT NO:

FILE NAME:

| SHEET:

© 2023 MICHAEL K. CHEN ARCHITECTURE, PLLC



DOCUMENTATION BY ARCHITECT

#### **Violation Number: VIO-10-0610 (Active)**

Address: 104 East 10th Street Community District: MN-3

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

District

Violation Date: 12/21/2009 Violation Text: Lintels shaved at parlor floor

and second floor without permit(s).

Violation Status: Warning Letter







## 2 10TH STREET FACADE - RESTORED CONDITION PHOTO BY ARCHITECT

#### NOTES:

All lintels and sills at the front facade were rebuilt per approved drawings to match historic record, including shaved lintels at the parlor and second floor windows.

ARCHITECT
// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

**104 E 10th Street** 104 E 10th St., New York, NY 10003

### LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

PROJECT NO:


DWG NO:

LPC -009

FILE NAME:

|SHEET:

19\_104E10







DETAILS - NEW WINDOWS, LINTELS & SILLS PHOTO BY ARCHITECT

ARCHITECT

// MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

PROJECT NO:

19\_104E10

FILE NAME:

| SHEET:

#### **Violation Number: VIO-10-0611 (Active)**

Address: 104 East 10th Street Community District: MN-3

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

Violation Date: 12/21/2009 Violation Text: Newel posts altered/removed

without permit(s).

Violation Status: Summons (NOV)











#### NOTES:

Missing/existing newel posts were restored with vintage newels to match condition and character of earliest available record which is the 1940's tax

> ARCHITECT // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

**104 E 10th Street** 104 E 10th St., New York, NY 10003

LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10 PROJECT NO:

FILE NAME:

| SHEET:





PHOTO BY ARCHITECT







**UNDERSTOOP GATE** PHOTO BY ARCHITECT

ARCHITECT

## // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

# **104 E 10th Street** 104 E 10th St., New York, NY 10003

## LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

19\_104E10 PROJECT NO:

FILE NAME:

| SHEET:

East Window

#### **Violation Number: VIO-10-0612 (Active)**

Address: 104 East 10th Street Community District: MN-3

Borough/Block/Lot: MANHATTAN / 465 / 109 Landmark: St. Mark's Extension - Historic

District

Violation Date: 12/21/2009 Violation Text: Garden floor window guards

replaced without permit(s).

Violation Status: Warning Letter



West Window





East Window



#### NOTES:

All windows at the front facade were replaced with approved, historic equals. Unpermitted window guards at the garden level windows were removed.

There is no historic record of the original design or intent. We know there was a violation filed in 2009 for unpermitted removal and replacement, but the exact nature of the original guards is unknown.

We are requesting to forgo replacement as any reconstruction would need to be derived from seconary references. Further, we believe unguarded windows offer a more consistent and uniform reading across all windows on the front facade and is not in conflict with the aesthetic make up of the block. As you will see in reference photos, there is a mix of guarded and unguarded windows in the St. Marks Historic District.

ARCHITECT

## // MKCA //

MICHAEL K. CHEN ARCHITECTURE, PLLC 1239 BROADWAY, SUITE 600 NEW YORK, NEW YORK 10001 T: 212 732 0060 eastcoast@mkca.com

PROJECT

## **104 E 10th Street**

104 E 10th St., New York, NY 10003

### LPC SUPPLEMENTAL

SEAL AND SIGNATURE

DATE:

PROJECT NO:

o: **19\_104E10** 

DWG NO:

LPC -013

FILE NAME:

|SHEET:

(C) 2023 MICHAEL K. CHEN ARCHITECTURE, PLLC





GARDEN FL. WINDOWS - RESTORED CONDITION

PHOTO BY ARCHITECT